# **Latest Vehicle Concern Fixes**

### **BODY**





## **Air Conditioning Blowing Warm Air**

#### **Customer Voice:**

A customer may report that the HVAC system is not blowing cool air.

#### Technical Description:

The air conditioning system may be low on refrigerant due to a slow refrigerant leak on a limited number of I-PACE models caused by the condenser pipe clamp not achieving proper clamp load due to a tolerance stack up issue.

#### Status:

- SSM 74851 has been published to address this concern, providing details on installing a washer to ensure proper clamp load can be achieved.
- Should a customer express a concern please refer to this SSM.













