

Latest Vehicle Concern Fixes

POWERTRAIN



3.0P Supercharger FEAD idler and Supercharger tensioner noise	17MY Onward Range Rover, RR Sport, RR Velar, Discovery, F TYPE, F PACE, XE, XF, XJ equipped with AJ126
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">• There is a noise from the engine. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">• The root cause of the noise is the idler pulley and/or tensioner on the Supercharger FEAD Belt. <p><u>Status:</u></p> <ul style="list-style-type: none">• Reference SSMs 74810 and 74811.• Raise an EPQR and include the following:<ul style="list-style-type: none">• Video or sound file of the noise.• Photographs that detail any evidence of contamination of the pulley and the origin of the contamination.• Service history from the vehicle.	

