

			No:	TSB-20-36-002
			DATE:	June 2020
			2018-	: 2017-2020 Outlander, -2020 Outlander PHEV, NI Eclipse Cross
CIRCULATE TO:	[] GENERAL MANAGER	[X] PARTS MANAGER		[X] TECHNICIAN
[X] SERVICE ADVISOR	[X] SERVICE MANAGER	[X] WARRANTY PROCESSOR		[] SALES MANAGER

PURPOSE

In cases where the Electronic Parking Brake (EPB) function has not been used in a long time and the brake pads are worn down; when the EPB is operated it may take increased amounts of time to function and exceed the threshold value. As a result, the warning light will illuminate and EPB may become inoperative.*

*This phenomenon does not effect the normal brakes.

This TSB instructs dealers how to perform maintenance to resolve this phenomenon.

AFFECTED VEHICLES

2017 - 2020 Outlander 2018 - 2020 Outlander PHEV All Eclipse Cross

REPAIR PROCEDURE

Follow the work flow chart below.

Copyright 2020, Mitsubishi Motors North America, Inc.

Page 1 of 3

FLOW CHART







