



## Service Literature

**To:** General Managers  
Service Managers  
Service Technicians  
Warranty Managers

**Region:**  U.S.  
 CAN

**Bulletin:** SLV20-007  
**Date:** August 1, 2020  
**Valid to:** N/A

**Action Required?**  Yes  No

**From:** Volvo Trucks – Service

**Subject:** Service Literature Published and Released in July, 2020

The following summarizes the service literature that has been published and/or revised for the month.

### SERVICE NEWS

BULLETIN #	TITLE	COMMENTS
SNV20-007	Recall EC0022 Expanded	New

### TOOL BULLETIN

BULLETIN #	TITLE	COMMENTS
STB20-003V	Essential Tool Program - Automatic Tool Shipment	New

### FIELD SERVICE BULLETIN

BULLETIN #	TITLE	COMMENTS
FSB 519-001	Dust Cover, Drive Axle, Replacement	New

### SERVICE PROGRAM

BULLETIN #	TITLE	COMMENTS
S7510	Secondary Fuel Filter replacement	Reopened
S7514	Exterior Sun Visor Fasteners, Re-Torque	New

### RECALLS

BULLETIN #	TITLE	COMMENTS
	None Issued	



**(CBR) CASE BASED REASONING**

**NEW SOLUTIONS**

<b>SOLUTION #</b>	<b>TITLE</b>
KC-2033	Volvo Chassis - Bendix ABS Fault SPN 807 FMI 13 Blink code 19-04

**UPDATED SOLUTIONS**

<b>SOLUTION</b>	<b>TITLE</b>	<b>COMMENTS</b>
KC-219	Oil In Control Housing Or TECU -- AMT-F	Updated the cleaning process
KC-314	On-Highway Vehicles With 2018 Interior Update - Enabling Traffic Sign Recognition (TSR) For Bendix 1.0	Updated information to specify eService is required if using ACOM PRO.