Technical product information

Topic	Bentayga - Button Module For Driving Profile Selection		
Market area	Bentley: worldwide (2WBE)		
Brand	Bentley		
Transaction No.	2058477/3		
Level	EH		
Status	Released for publishing		
Release date	03-Jul-2020		

New customer code

Object of complaint	Complaint type	Position
engine -> operation, engine control -> engine start/stop button	component / consumables -> damaged	
engine -> operation, engine control -> drive mode switch	component / consumables -> damaged	
engine -> operation, engine control -> drive mode switch	functionality -> too stiff	
driver assist systems, convenience features -> vehicle setup -> vehicle set-up switch	component / consumables -> damaged	
running gear -> adaptive suspension, pitch and roll compensation	functionality	
engine -> starter, ignition system, preheater system -> ignition/starter switch	component / consumables -> damaged	
engine -> starter, ignition system, preheater system -> ignition/starter switch	functionality -> too stiff	

New workshop code

Object of complaint	Complaint type	Position
engine -> starter, ignition system, preheater system -> starter solenoid switch	functionality -> without function / defect	
running gear -> adaptive suspension, pitch and roll compensation -> suspension adjustment switch	functionality -> without function / defect	

Vehicle data

Bentayga series

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
4V1*	2017	E		*	*	*
4V1*	2018	Е		*	*	*
4V1*	2019	Е		*	*	*
4V1*	2020	Е		*	*	*
4V1*	2021	Е		*	*	*

Documents

Document name master.xml

Customer statement / workshop findings

"Button Module For Driving Profile Selection" requires replacement.



Technical background

There is an ongoing factory investigation into failures of the "Button Module For Driving Profile Selection".

Any ``Button Module For Driving Profile Selection" that is removed due to a fault is to be returned fully assembled using the Warranty parts return process.

Production change

Not applicable.

Measure

When removing the "Button Module For Driving Profile Selection" due to a fault condition, do not attempt to disassemble and rectify, once removed assemblies should be returned using the Warranty parts return process.

Note: For information with regard to the Warranty parts return system, refer to "Bentley Hub – Aftersales – Warranty – 19-42 Parts return process".

Parts information

Always refer to the Electronic Parts Catalogue for the latest part information – ETKA.