

LATEST VEHICLE CONCERN FIXES
ELECTRICAL



<p>20B SOTA Update</p>	<p>16 – 20MY E-PACE, F-PACE, I-PACE, F-TYPE, XE, XF, XJ, Range Rover, RR Sport, RR Velar, RR Evoque, Discovery & Discovery Sport equipped with InControl Touch Pro</p>
<p>Customer Voice:</p> <ul style="list-style-type: none"> • 20B Software Delay until July 15th <p>Technical Description:</p> <ul style="list-style-type: none"> • 20B Software Release <p>Status:</p> <ul style="list-style-type: none"> • 20B Will be released via SOTA on July 15th • Software was delayed to include software fix for L551 APIX cable issue • Audio popping noise • iOS13 Bluetooth improvements • Additional improvements 	

