

Index of Manufacturer (MFR) Communications

Manufacturer:	Mitsubishi Motors North America, Inc.
Date Range:	07/01/2020 - 07/31/2020
Date Submitted:	08/07/2020

No.	MFR Communication ID	MFR Communication Date	Make	Model	Model Year
1	Interim Customer Letter	07/14/2020	Mitsubishi	Outlander	2013
					2012
					2011
					2010
					2009
					2008
				Outlander Sport	2016
					2015
					2014
					2013
					2012
					2011
				Lancer	2010
					2009
					2008
				Lancer Sportback	2013
					2012
					2011
					2010
					2009
2	ATIN-20-SR-003-C	07/15/2020	Mitsubishi	Outlander	2013
					2012
					2011
					2010
					2009
					2008
				Outlander Sport	2016
					2015
					2014
					2013
					2012
					2011
				Lancer	2010
					2009
					2008
				Lancer Sportback	2010

					2009
3	TSB-20-42A-004	07/17/2020	Mitsubishi	Mirage	2019
					2018
					2017
4	TSB-20-51-002	07/17/2020	Mitsubishi	Eclipse Cross	2019
					2018
5	ATIN-20-SR-003D	07/31/2020	Mitsubishi	Outlander	2013
					2012
					2011
					2010
					2009
					2008
				Outlander Sport	2016
					2015
					2014
					2013
					2012
					2011
				Lancer	2010
					2009
					2008
				Lancer Sportback	2010
					2009
6	SR-20-003REV_1	07/31/2020	Mitsubishi	Outlander	2013
					2012
					2011
					2010
					2009
					2008
				Outlander Sport	2016
					2015
					2014
					2013
					2012
					2011
				Lancer	2010
					2009
					2008
				Lancer Sportback	2010
					2009

[The effect of the defect or noncompliance should be described below.]

Concise Summary (2000 character limit)

This Letter was sent to customers informing them of the launch of Recall SR-20-003, part are currently unavailable; but they will be notified when parts become available for repairs to begin. This notice also provided customers instruction on how to obtain repairs.

This Advanced Technical Information Notice was sent to dealers as an update to ATIN-20-SR-003B informing that due to a parts availability delay of the Crossmember, customer vehicles requiring a replacement of the crossmember are unable to be completed at this time. Additionally, this notice informed dealers that an Interim Owner Notification Letter was mailed to affected owners on July 17th, 2020 to inform customers that MMNA is making every effort to establish a remedy and will contact them again by mail with a follow-up recall notice once parts are in stock and the final remedy is available.

This TSB instructs dealers to replace the Fuel Filler Door Panel Assembly with a new countermeasure part, replace the clip and paint the Fuel Filler Door Panel, as appropriate.

This TSB instructs dealers to slant and change the form of the bottom rearward roof rack spacer in order to absorb the difference in contours.

This ATIN-20-SR-003D supersedes ATIN-20-SR-003C and ATIN-20-SR-003B, providing notification of modifications to the TSB and repair procedure; noting when a Crossmember replacement is required the anti-corrosive agent application is not required.

This bulletin provides directions for inspection and repair of affected vehicles' Crossmembers in the Safety Recall.