

Preliminary Information

PIC6403B Diagnostic Tip – Programming Modules on General Motors Next Generation Digital Electrical Architecture (VIP)

Models

Brand:	Model:	Model Years:	VIN:		Engine	Transmissions:
			from	to	Engine:	Hansinissions.
Cadillac	CT4	2020	ALL	ALL	ALL	ALL
Cadillac	СТ5	2020	ALL	ALL	ALL	ALL
Chevrolet	Corvette	2020	ALL	ALL	ALL	ALL

Involved Region or Country	North America
Condition	Programming modules on Next Gen Digital Architecture
Cause	New technology

Correction:

When it is required to SPS program a module on a 2020 Cadillac CT4, CT5, or Chevrolet Corvette the power mode needs to be OFF with the vehicle fully asleep.

Ensure that the vehicle is not woken up during the programming event by opening a door or using a transmitter. Follow all SPS on screen instructions.

Use of a MDI2 is required for all programming and diagnostics.

<u>Additional SI Keywords</u>

VIP

Version History

Version	3
	02/05/2020 - Created on
Modified	05/19/2020 - Added Cadillac CT4 and Chevrolet Corvette.
	06/16/2020 - Updated Correction.

















GENERAL MOTORS