



# Service Information

Offboard Diagnostic Information System Service (ODIS Service)

Number: VOS-20-28

Subject: Software Version Update, Enhancements and Fixes

Date: Aug. 12, 2020

**Supersedes VOS-20-25 due to new diagnostic content.**

The following ODIS Service software versions are available for download.

| Current ODIS Service Software Versions |                                    |
|--|------------------------------------|
| Application: <b>V6.1.0</b>             | Diagnostic Content: <b>V2.40.8</b> |

## **Key Fixes/Enhancements for Diagnostic Content: V2.40.8:**

### **1. A3 - Passat/New Midsize Sedan 2011 – 2020, DDSA & DDSB 2.0I Motronic / 130 kW**

Engine Electronics - 01 - Repair Groups missing and not available in Select Self-Test > Test Overview > Drive Train Type > 01 Engine Electronics.

### **2. AJ - Jetta SportWagen 2010 – 2014, CJAA 2.0 L TDI CR / 103 kW**

P0544: Exhaust Gas Temperature Sensor Circuit - Bank 1 G235\_5K\_26CJAA\_1\_0609\_11\_00011 confusing text.

- Test is for Exhaust Gas Temperature (EGT) Sensor 1 -G235 but in some segments of test TEMPERATURE OF EXHAUST GAS TEMPERATURE (EGT) SENSOR 3 is called out.

### **3. A3 - Passat/New Midsize Sedan 2011 – 2020, DDSA & DDSB 2.0I Motronic / 130 kW**

Readiness test SYS\_J623\_1\_0816\_11\_X\_X\_MSG\_OT\_SOD\_ReadinessCodeErzeugen\_00000 fails with error message: ODS5001E Infrastructure.Guided Fault Finding: Test program/step <null> could not be loaded.

- Test fails at the tank leak diagnosis basic setting.

### **4. General translation issues**