



SLINGSHOT



POLARIS



Team Tips

ARTICLE: SLI-15-07-01

DATE: July 01, 2015

Published for Polaris Dealerships, Distributors, and Service Technicians


SUBJECT: SLINGSHOT - REPROGRAMMING (REFLASH) PROCEDURE

MODELS: 2015 SLINGSHOT

The Slingshot Division of Polaris Industries has determined the reprogramming (reflash) procedure may be negatively affected if performed with a device connected to the USB connector.

It is important to disconnect all devices from the USB connector ① prior to performing an ECU, Stability Control, Instrument Cluster or Audio System reprogramming (reflash) procedure.

A technician should be familiar with Digital Wrench® and computer operation in general before attempting any reprogramming (reflash) procedure. Refer to the appropriate Slingshot Service Manual for additional information.



****Please distribute to all dealership personnel as required****