

WLC7 Workshop campaign - Replacing lower pressure pipe

Version 1

WLC7 Workshop campaign - Replacing lower pressure pipe

Overview

A pressure pipe, which does not comply with the specifications in terms of installation position and size, may be installed between the charge-air coolers on the affected vehicles.

This can cause vibrations and noise in the medium rev range at high engine load.

In order to prevent this, the lower pressure pipe between the charge-air coolers must be replaced with an optimized version.

In addition, the installation position of the other components of the charge-air cooling system must be checked and corrected if required.

Model type	Macan S (95B)
Model year	2019 - 2020
Number	284

Parts required

Part No.	Designation	Quantity/vehicle	Parts return*
00004391196	Lower pressure pipe	1 ea.	No
N 10518901	Hose clamp	2 ea.	No
PAF106322	Internal hexagon round-head bolt	2 ea.	No
PAB129669B	Grommet	2 ea.	No
PAB129734B	Spacer	2 ea.	No
N 91173301	Hexagon nut	2 ea.	No

* The parts must be stored until such a time as the related warranty or campaign claim has been credited. If a barcode is generated with the credit note, the affected part must be sent to Porsche AG as usual. If no barcode is generated with the credit note, the part can go directly into the genuine remanufactured parts process or be scrapped.

Warranty processing

Validity:

This workshop campaign will be carried out up to 6/5/2025 and will be closed by the specified date.

Please note that warranty claims can only be processed before this date.

Scope 1:

Damage Code	WLC7 6 6 000
Repair Code	2
Working time	199 TU

Please enter the campaign that was carried out in the Warranty and Maintenance booklet for the vehicle.

Porsche Mobility

If requested, the mobility of the affected customer can be guaranteed by offering a suitable replacement vehicle.

Please invoice this additional service with the campaign scope via WWS.

Further information

Work instruction	TI No. 43/20, Group 2, Service, WLC7
Vehicle list and allocation	See PCSS or attached list for reference
Technical Information	See PCSS or attached PDF for reference

[95B 2 43-20 WLC7 Replacing Lower Pressure Pipe \(Workshop Campaign\).pdf](#)

361.7 KB

(62 views)

[WLC7 VIN List.xlsx](#)

14.1 KB

(41 views)

Created by [Ryan Cooney](#) on Aug 14, 2020 9:35 PM. Last modified by [Ryan Cooney](#) on Aug 14, 2020 9:42 PM.

Categories: Workshop Campaigns, Macan

Tags : [macan s](#), [wlc7](#), [lower pressure pipe](#)

595 Views

[Report Abuse](#)

Content and Topics	Personal	Manage	Create
Your Groups >	Edit Profile >	Admin Console >	Discussion >
Your Content >	Change Password >	PPN Administration>	Files >
Your Places >			Document >
			Collaboration >
			Document
			Blog Post >
			Poll >
			Event >
			Photo Album >
			Idea >
			Space >
			Group >

© 2020 Dr. Ing. h.c. F. Porsche AG. [Legal notice.](#) [Copyright.](#) [Terms of use.](#) [Privacy Policy.](#) [Cookie Policy.](#) [009](#)