

# Technical Journal

TITLE:

**Seat belt catch, foreign objects**

<b>REF NO:</b> TJ 35561.2.0	<b>ISSUING DEPARTMENT:</b> Technical Service	<b>CAR MARKET:</b> United States and Canada	
<b>PARTNER:</b>		<b>ISSUE DATE:</b> 2020-07-02	<b>STATUS DATE:</b> 2020-07-15
<b>FUNC GROUP:</b> 8843	<b>FUNC DESC:</b> Catch for safety belt	Page 1 of 2	

## Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
232							2020-9999		-	0-0
534							2021-9999		-	0-0

## CSC Customer Symptom Codes

Code	Description
VU	Seat belt and other safety systems/Buckle latching problems

## VST Operation Number

VST Operation Number	Description
99921-2	General according to TJ

## DTC Diagnostic Trouble Codes

Rows beginning with \* are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

## DESCRIPTION:

When analyzing replaced seat belt catches, we have found catches with coins, candy, nuts etc inside, causing the problem.

\* VST Operation No. updated.

## Technical Journal 35561.2.0

### **SERVICE:**

Before replacement the belt catch must be checked if there is any kind of foreign objects inside. If there are objects inside the belt catch try to carefully remove the object with vacuum cleaner or compressed air. **Do not use** a screwdriver or similar. Then check that the function of the belt catch is ok.

*Warranty claim info:*

*To get warranty claim accepted for a job described in this TJ, please use the attached VST OP number.*

### **VEHICLE REPORT:**

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report Polestar" and sub concern area "Support not needed Polestar", use function group 8843.