

# Service Campaign Bulletin



Mercedes-Benz

Campaign No. 2020070014 September, 2020

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: **Model 907 Model Year 2019-2020**  
**Replace Noise Emissions Information Label**

Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz and Freightliner Sprinter vans, has determined that the noise-emission information label located on the driver seat frame may not have been affixed in certain Sprinter vehicles. An authorized Mercedes-Benz or Freightliner Sprinter dealer will check the affected vehicles whether the noise emission information label is affixed, and apply the label if necessary. When ordering the information label, the related vehicle identification number must be included with the order.

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired.
- Please review the entire Service Campaign bulletin and follow the repair procedure exactly as described.

Approximately **992** vehicles are affected.

Order No. V-SC-2020070014

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

## Modification notes

14.07.2020	Parts ordering note adapted.		
------------	------------------------------	--	--




## Operation no. of the operation texts or standard texts and flat rates

Op. no.	Operation text	Time	Damage Code
02 1874	Operations: Check noise emission information label	0.1h	58 917 63 7
02 1875	Operations: Retrofit noise emission information label	0.1h	58 917 63 7

### 1 Information label (Noise emission)



D00.00-A104-06

	<b>Check</b>		
1	Check, whether the vehicle is affected by the measure.	 Only the entry in the "Extended VEGA Application" (EVA) system in the "Current" tab is decisive for authorized Mercedes-Benz service partners. An additional test of the affected vehicles in the workshop information system (WIS) or vehicle list is thereby not necessary.	
2	Check whether information label (1) is installed.	If information label (1) is installed:  ↓ end the measure. If information label (1) is not installed:  ↓ Continue with operation step 3.	
	<b>Retrofit</b>		
3	Retrofit information label (1) as shown.	 Bonding surface must be absolutely free of dust and grease. Otherwise, a sufficient degree of adhesion cannot be assured. Cleaner	<a href="#">BR00.45-Z-1025-04A</a>

**Repair materials**

Number	Designation	Order number
BR00.45-Z-1025-04A	Cleaner	A 005 989 19 71

**Parts ordering note**

Part no.	Designation	Quantity
A 907 584 24 05	Noise emission information label (quote vehicle identification number when ordering)	1