

## GPOP - Issue Review System

**Part Number:** 68322374A\$, 68258537A\$, 68258536A\$, 68258535A\$, 68258532A\$, 68258527A\$, 68243265A\$, 68243264A\$, 68243262A\$, 68243261A\$, 68243259A\$, 68243258A\$, 68243257A\$, 68237160A\$, 68213055A\$, 68199793A\$, 68197810A\$, 68192083A\$, 68137438A\$, 68089580A\$

**Part Description:** Intelligent Power Distribution Center

**Issue Description:** If the PDC requires replacement due to a failed internal fuel pump relay, the relay can now be serviced as a separate component. Please use relay replacement KIT part number: 68510768A\$.

~ \_\_\_\_\_ ~  
Contact Us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.

