

Subject: Engineering Information - Engine Oil Found Under Vehicle

This PI has been revised to end the need for information from the field. Please discard PIE0574.

| Brand: | Model: | Model Year: | | VIN: | | Engine: | Transmission: |
|-----------|-----------------------------|-------------|------|------|----|---|---------------|
| | | from | to | from | to | | |
| Chevrolet | Silverado 2500/3500 HD | 2020 | 2021 | - | - | Equipped with 6.6L Engine (RPOs L5P, L5D) | - |
| | Silverado 4500/5500/6500 HD | | | | | Equipped with 6.6L Engine (RPO L5D) | |
| GMC | Sierra 2500/3500 HD | | | | | Equipped with 6.6L Engine (RPOs L5P, L5D) | |

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

| | |
|-----------------|--|
| Version | 2 |
| Modified | Released July 13, 2020 Revised September 23, 2020 – Ended the need for further information from the field |