



October 8, 2020

Product Change Notice - Shorter screws, adjusted location for entry door strike plates

Dear Valued Customer:


LCI intends to change the screw length for the strike plate on entry doors and the location of one of the screws in the strike plate.

It was determined using a shorter screw (Fig. 2) for the strike plate would make installing the door within approved tolerances easier for the OEM due to less of the screw protruding from the door.

Moving the bottom screw forward also adds to the plate's durability, ensuring the plate will not shift when the door is closed.

There is no change in fit or function with the screw length and location change. There is no change in installation for the OEM customer and no price change.

The part number for the current screw is 235110. The part number for the new screw is 206569. The change is taking place immediately.



If you have any questions, please feel free to call me directly or your LCI representative. We value and appreciate your business and partnership.

Sincerely,

Scott McKinnon
Product Manager
c: 269.832.6800
smckinonn@lci1.com

Frequently Asked Questions:

- 1. Will a new part number be required?** The PN for the door will not change. The part number for the current screw is 235110. The part number for the new screw is 206569.
- 2. Does the price change for the item?** No, there is no price change.
- 3. Is the new part wholly interchangeable with the previous version of the part?** Yes, the doors are interchangeable.
- 4. Does the customer need to replace inventory?** No, the change is taking place on a running basis, starting immediately.