



# SERVICE BULLETIN

Classification: EL20-038	Reference: NTB20-074	Date: October 14, 2020
-----------------------------	-------------------------	---------------------------

## 2021 ROGUE AND 2020 SENTRA; BCM SERVICE INFORMATION

**APPLIED VEHICLES:** 2021 Rogue (T33)  
2020 Sentra (B18)

### SERVICE INFORMATION

- When replacing the BCM, **ALWAYS** replace it with a new one.
- Module configuration **MUST BE** performed before pairing the BCM and intelligent key unit. Once the BCM and intelligent key unit have been paired, portions of the configuration are locked and can no longer be changed.
- When replacing the BCM, it is critical to follow the work procedure as detailed in the ESM.
  - For Rogue, go to **ELECTRICAL & POWER CONTROL > BODY CONTROL SYSTEM > BASIC INSPECTION > ADDITIONAL SERVICE WHEN REPLACING BCM.**
  - For Sentra, go to **ELECTRICAL & POWER CONTROL > BODY CONTROL SYSTEM > BASIC INSPECTION > INSPECTION & ADJUSTMENT > ADDITIONAL SERVICE WHEN REPLACING CONTROL UNIT (BCM).**

### **NOTICE**

To prevent damage to the BCM, perform module configuration **BEFORE** pairing the BCM and intelligent key unit.

### AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
October 14, 2020	NTB20-074	Original bulletin published

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.