



STAR ONLINE PUBLICATION

Case Number: S2008000154

Release Date: 10/15/2020

Symptom/Vehicle Issue: B1053-64 RFHM (Kin Communication) - Signal Plausibility Failure Set In The RF Hub. EVIC Displays Service Passive Entry

Discussion: The customer may state the “Service Passive Entry” message is being displayed EVIC at times. Upon scanning the vehicle for DTC’s you will find B1053-64 RFHM (Kin Communication) - Signal Plausibility Failure set in the RF Hub.

Engineering is currently working on a RFH software update with an anticipated release date in the 1st quarter of 2021. Replacement of the RFH or any other components will not resolve this issue.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found