



# Technical Service Bulletin

---

## PSS 90 Pre sense malfunction/driver assist systems sporadically inop, DTC B200FF9 is stored in the driver assist module

90 20 80 2061489/1 November 24, 2020.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Audi e-tron Sportback	2020 - 2022	All	Not Applicable
A6, A7, A8, and Audi e-tron quattro	2019 - 2022	All	Not Applicable

## Condition

### Customer states:

- The vehicles driver assistance systems are sporadically not working

One of the following messages may be displayed in the instrument cluster:

- Audi adaptive light malfunction.
- Audi pre sense system malfunction.
- Adaptive vehicle assistance restricted.
- Adaptive vehicle assistance Predictive regulation restricted.

After an ignition cycle or bus sleep, the systems are available again.

### Workshop findings:

The following DTC is stored sporadically in the driver assistance systems control module, J1121 (address word 00A5):

- **DTC B200FF9** (internal malfunction) with symptom code 2117657.

## Technical Background

The control module's diagnostic checks are too sensitive.

## Production Solution

This bulletin will be updated when more information is available.



# Technical Service Bulletin

---

## Service

1. Explain to the customer that a solution is forthcoming for the 4th quarter of 2021 and that no repairs are necessary at this point. Do not replace any components for this condition since this will not resolve the customer's concern.
2. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links >> Service*), or through the Technical Assistance page in Elsa.

## Warranty

<b>Claim Type:</b>	<ul style="list-style-type: none"><li>• 110 up to 48 Months/50,000 Miles.</li><li>• G10 for CPO Covered Vehicles – Verify Owner.</li><li>• If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.</li></ul>		
<b>Service Number:</b>	9093		
<b>Damage Code:</b>	0039		
<b>Diagnostic Time:</b>	GFF	0151 0000	Time stated on the diagnostic protocol (Max 15 TU)
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	No allowance	0 TU
<b>Claim Comment:</b>	As per TSB #2061489/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

## Additional Information

All part and service references provided in this TSB (2061489) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2020 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or



# Technical Service Bulletin

---

transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.