## **TECHNICAL TOPICS BODY/CHASSIS**





Roof Opening Panel Does Not Open Fully	17 – 20MY XE
Customer Voice:  – A customer may report that the roof opening panel does not appear to open	
fully.	
Technical Description:	<u>a</u>
<ul> <li>The roof opening panel on Jaguar XE models will open to different distances depending if the vehicle is equipped with satellite radio.</li> </ul>	
Status:	
<ul> <li>The roof opening panel operation is designed not to block the roof mounted satellite antenna on models with this option.</li> </ul>	
– The roof opening panel will stop before covering the antenna.	L18597
<ul> <li>Models variants without the roof mounted satellite antenna will have a roof opening panel that opens further.</li> </ul>	1.1385978
<ul> <li>Please note these differences and designed operation before diagnosing the roof opening panel operation.</li> </ul>	











PRINTED COPIES ARE UNCONTROLLED