

## **SSM 49318 - 2011-2020 F-150/Mustang - 5.0L - Updated Secondary Chain Tensioner Service Part Compatibility**

For 2011-2020 F-150/Mustang vehicles equipped with a 5.0L engine when installing a replacement secondary timing chain tensioner (6K254) or secondary timing chain guide (6K297), it is necessary to replace both components as a pair, using the latest level parts. Make sure to use secondary timing chain tensioner part number ML3Z-6K254-A and secondary timing chain guide part number ML3Z-6K297-A.

### APPLICABLE VEHICLES

2011 - 2014 TRUCK: F6 F150/LINCOLN MARK LT

2018 - 2020 TRUCK: FC P552N F-150

2015 - 2017 TRUCK: FC P552N F-150

2012 - 2013 CAR: ZF S197N MUSTANG

2011 - 2014 CAR: ZF S197N MUSTANG

2019 - 2020 CAR: ZG S550N MUSTANG

2015 - 2020 CAR: ZG S550N MUSTANG