

SSM 49404: 2021 Explorer Limited - DTCs B154D:15 And/Or B11CE:15

Some 2021 Explorer Limited trim vehicles equipped with the 300A convenience package including 2nd row power-fold backrest and 3rd row manual folding seats may exhibit diagnostic trouble codes (DTCs) B154D:15 and/or B11CE:15 stored in the power fold seat module (SCMJ). If these DTCs are noticed during diagnosis of unrelated concerns, they should be ignored. No repairs should be attempted to address these DTCs.

Vehicles:

2021 Explorer (U625N) (TW)

Symptom Code:

B11CE

B154D