

GPOP - Issue Review System

Part Number: 04893687A\$, 68377382A\$, 05281614A\$, 05281541A\$

Part Description: Turbocharger

Issue Description: If the turbo is being replaced for an oil leak concern, please inspect the area around the turbo oil feed o-ring for a leak. The o-ring is serviced separately and complete turbo replacement may not be necessary.

~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
