

TECHNICAL SERVICE BULLETIN

Group:	11-ENGINE
Bulletin No:	SB-16-008
Issue Date:	5-3-2016
Vendor Ref.:	HMM-160325-J1

DTC P0611 ENGINE ECU

SUBJECT VEHICLES: 13MY-15MY COE Trucks (155, 155h, 195 or 195h)

Note: This service bulletin is provided as technical information and is not authorization for a warrantable repair.

OVERVIEW:

If DTC(Diagnostic Trouble Code) P0611:Fuel Injector Driver Charge Circuit - Circuit Low has set in the engine ECU(Electronic Control Unit) and the workshop manual diagnostic procedure has led to ECU replacement, an enhanced engine ECU is available to prevent this DTC from recurring. Replace the engine ECU with the part number listed below.

PARTS

PART NUMBER	PART DESCRIPTION	QUANTITY
89661E0044	ENGINE ECU	1

Claim Application

** Reimbursable in accordance within the terms and policies of the Hino Truck limited warranties.*

Engine ECU Replacement:

Labor Charge: 2.3 Hours

*Includes: Functional check, reprogramming, and system check

Warranty Code: 86311

Trouble Code: 43

Operation Code: 86306ARE

Part Number: 89661E0043



A Toyota Group Company