

DEALER HOLD

Release Date: December 23, 2020

SLI

Communication #: TDH-20-04

Model Year(s): 2021

— Confidential and Proprietary —

VERSION: R01 (December 23, 2020)

IMPORTANT STOP SALE NOTICE!

Stop selling affected vehicles immediately.

SUBJECT: DEALER HOLD - BODY REFLECTORS PURPOSE

Polaris has found that some Slingshot models may have been manufactured without the driver's and/or passenger's front side reflector(s).

To resolve this issue, the driver's and passenger's side reflector decals must be present prior to sale and registration.

AFFECTED MODELS

MODEL YEAR	MODELS	VEHICLE IDENTIFICATION NUMBER RANGE
2021	Slingshot R / S / SL	Reference Unit Inquiry on the dealer website or the Service Communications list on the STOP site to lookup affected VINs.

WARRANTY CLAIM PARTS INFORMATION

SLINGSHOT R / S / SL - PASSES INSPECTION		
Bulletin	TDH-20-04A	
Claim Type	Dealer Hold	
Labor Allowance	0.2 hours (12 minutes)	
Part Number / Description	0000541 (QTY 1) Bulletin Misc Labor	
Parts Availability	NA	
University of Polaris Video Training Required	NO	

TDH-20-04 (R01) © 2020 Polaris Inc. Page 1 of 2

The information contained within this document is confidential and protected by U.S. and international copyright laws, and is the property of Polaris Inc. This document is provided for the sole use of authorized Polaris dealers and distributors. This document is not to be distributed, duplicated, or copied, digitally or otherwise, without the written consent of Polaris Inc.

TDH-20-04 PROCEDURE

DECAL INSPECTION PROCEDURE

1. Inspect that the driver's side reflector decal is present and secure.



2. Inspect that the passenger's side reflector decal is present and secure.



- 3. If both reflector decals are present, the vehicle may be sold. File a Dealer Hold claim for TDH-20-04A.
- 4. If either decal is missing, the vehicle cannot be sold. Polaris will update this communication with a complete repair procedure once it is available.

IMPORTANT

If the vehicle is missing any decals, do NOT file TDA-20-04A.

This communication will be updated in the next few weeks to include a replacement process.

TDH-20-04 (R01) © 2020 Polaris Inc. Page 2 of 2