



## Preliminary Information

### PIT5799A Flashing Diamond - Spot - or UFO On Rear View Camera Display

#### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	CT4	2021	All	All	All	All
Cadillac	CT5	2020 - 2021	All	All	All	All
Cadillac	Escalade	2020 - 2021	All	All	All	All
Cadillac	Escalade ESV	2020 - 2021	All	All	All	All
Chevrolet	Bolt	2020	All	All	All	All
Chevrolet	Corvette	2020 - 2021	All	All	All	All
Chevrolet	Silverado	2020 - 2021	All	All	All	All
Chevrolet	Suburban	2020 - 2021	All	All	All	All
Chevrolet	Tahoe	2020 - 2021	All	All	All	All
GMC	Sierra	2020 - 2021	All	All	All	All
GMC	Yukon	2020 - 2021	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	Equipped with UVA, UVI, UVS, UV2
Condition	A customer may comment that a flashing spot is present on the radio display when in reverse and is corrected by an ignition cycle.
Cause	Engineering is investigating the concern

#### Correction:

Please communicate to the customer that we apologize for this inconvenience and that General Motors is working on a solution for this concern.

Once a solution is available, this PI will be updated with additional details - allowing dealership personnel to contact the customer to schedule a service appointment and repair the vehicle.

#### Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
3487208	Verify spot on radio display in reverse	.3 Hr.
*This is a unique Labor Operation for Bulletin use only.		

#### Version History

Version	1
Modified	11/19/2020 Created on.

