

DanyD

BRP Service Dept - N/A



Posts: 1,016
Registered: 10-19-2011
Location: NA

SE5 centrifugal clutch vibration [Edited]

Options ▾

02-27-2012 02:04 PM - edited 02-17-2014 03:08 PM

The centrifugal clutch may be responsible for an engine vibration felt between 1800 - 3200 rpms. The reason for the vibration is due to the uneven opening or clamping of the centrifugal clutch.

Follow link below to access the TST for more details:

[SE5-centrifugal-clutch-vibration](#)

Dany D
Roadster Product Specialist

Me too