

# MULTI-MODEL (EQUIPPED WITH REAR VIEW MONITOR) *REAR VIEW MONITOR DISPLAY IS BLURRY*

Some customers may complain about a blurry rear view monitor display. This may be caused by an aftermarket accessory device.

Some aftermarket electrical devices (e.g., an accessory cell phone charger) may create excessive electrical noise. The noise may interrupt some of the vehicle electrical systems. Below is an example of an aftermarket cell phone charger that is interrupting the rear view monitor system:

## Blurry Display



With aftermarket cell phone charger connected to 12V outlet



OK



Without aftermarket cell phone charger



### Warranty Compliance Note:

Repairs for this concern are not covered under Mazda's warranty policy. Advise the customer not to use the aftermarket device that is causing the concern.

An editorial board comprised of MNAO service staff members generates, collects, and verifies information for this publication. © 2016 Mazda Motor of America, Inc.

To contribute repair tip ideas, send an e-mail to [mtips@mazdausa.com](mailto:mtips@mazdausa.com) or fax to (949) 442-6599. If we select your repair tip, you will receive \$50 value in Reward Performance by Mazda (RPM) points for your efforts. All contributions become property of MNAO, which assumes permission to publish them without further consideration