

Air Conditioning Intermittently Does Not Cool

Topic number	LI83.30-P-071494
Version	4
Function group	83.30 Air conditioning
Date	10-30-2020
Validity	Model series 205, 213, 238, 257 and 222 from manufacturing date 15.10.2018, no hybrids (code ME05, ME06, ME08, ME09)
Reason for change	Incorrect language translation
Reason for block	

Complaint:

Air conditioning intermittently does not cool.

Cause:

Possible software bug in air conditioner control unit.

Remedy:

Flash to current software release using the most current version of Xentry software.

Symptoms

Body / Air conditioning / Air conditioning / Insufficient cooling output

Control unit/fault code

Control unit	Fault code	Fault text
N22/1 - Air conditioning (AAC) (HVAC222)	-	-

Operation numbers/damage codes

Op. no.	Operation text	Time	Damage code	Note
00-0001			83082 90	

Validity

Vehicle	Engine	Transmission
C (205)	*	*

XENTRY TIPS

CLS (257)	*	*
E (213)	*	*
E (238)	*	*
S (222)	*	*