



Service Literature

To: General Managers
Service Managers
Service Technicians
Warranty Managers

Region: U.S.
 CAN

Bulletin: SLV21-001
Date: January 31, 2021
Valid to: N/A
Action Required? Yes No

From: Volvo Trucks – Service

Subject: Service Literature Published and Released in January, 2021

The following summarizes the service literature that has been published and/or revised for the month.

SERVICE NEWS

BULLETIN #	TITLE	COMMENTS
SNV21-001	Improved method for determining which DTC to troubleshoot in a MIL on situation	New

TOOL BULLETIN

BULLETIN #	TITLE	COMMENTS
	None Issued	

FIELD SERVICE BULLETIN

BULLETIN #	TITLE	COMMENTS
FSB 210-046	Replacement Engine Labels	Revision

SERVICE PROGRAM

BULLETIN #	TITLE	COMMENTS
S7553	Road Speed Limit Default Setting	New

RECALLS

BULLETIN #	TITLE	COMMENTS
SRA-V20-06b	Safety Recall Alert RVXX2006, Norgren Collet Inspection/Replacement	Revision
C6621	RVXX2006, Norgren Collet Inspection/Replacement	New



(CBR) CASE BASED REASONING

NEW SOLUTIONS

SOLUTION #	TITLE
CBR-2085	Diagnostic Code (DTC) B105254 Active And Unable To Be Cleared - Vehicles Manufactured On Or After 1 January 2021

UPDATED SOLUTIONS

SOLUTION	TITLE	COMMENTS
CBR-445	Vehicles Equipped With a Common Rail Fuel System - Aftermarket Secondary Fuel Filters, Important Information On Approved Filters - US17+OBD16 And Newer Emissions	Modified tags to improve searchability.
CBR-2040	P21CA00 And Other Power Faults Leading To Communication Faults And SCR Inducement (Derate)	Revised repair instructions - Redundant information concerning sensor and ACM checks removed.
CBR-723	Diagnostic Trouble Codes (DTC) P0016-76 - Crankshaft Position - Camshaft Position Correlation - Turbo Compound (TC) - Model Year 2018 and Newer	Updated the "NOTE" comment.
CBR-527	Diesel Exhaust Fluid (DEF) Contamination In Fuel System, Inspection And Repair; Engine Misfire, No-Start, Uneven Operation, Multiple Injector Codes, Fuel Pressure Codes - US17 And Newer (Common Rail Fuel System)	Added note advising to open an eService case and attach the RO for any repairs related to DEF contamination.
CBR-136	Aftertreatment Control Module (ACM) Offline/Not Visible/Missing From Control Unit Information in Premium Tech Tool (PTT) - US10+OBD13 And Newer Emissions	Corrected applicable emission information.
CBR-445	Vehicles Equipped With a Common Rail Fuel System - Aftermarket Secondary Fuel Filters, Important Information On Approved Filters - US17+OBD16 And Newer Emissions	Updated the list of approved secondary fuel filters.
CBR-290	Volvo Chassis - Redundant Brake Switch Test - Code MID136 SID55 FMI2, or(DTC) P1055	Updated solution format.