

# WLG9 Workshop campaign - Replacing lower part of front lid lock

Version 1

## **WLG9 Workshop campaign - Replacing lower part of front lid lock**

### **Overview**

A bowden cable that does not meet the required specifications was installed on lower part of the lid lock on the affected vehicles and this can crack over the service life of the vehicle.

If this happens, the front lid must then be opened using the emergency release.

To prevent this from happening, the lower part of the lid lock on the front of the affected vehicles must be replaced with a lower part that meets the required specifications.

Please arrange for this measure to be carried out on the affected vehicles during the next workshop visit or before handing the vehicles over to customers, where applicable.

<b>Model type</b>	718 Boxster (982) / 718 Cayman (982) 911 (991) 911 (992)
<b>Model year</b>	2019 - 2020
<b>Number</b>	12,001

## Parts required

<b>Part No.</b>	<b>Designation</b>	<b>Quantity/vehicle</b>	<b>Parts return*</b>
V04015004	Lid lock - 718 Boxster / 718 Cayman (982) - 911 (991)	1 unit	No
V04015004A	Lid lock - 911 (992)	1 unit	No

\* The parts must be stored until such time as the **related warranty or campaign claim has been credited**. If a **barcode is generated** with the credit note, the affected part must be sent to Porsche AG as usual. If no barcode is generated with the credit note, the part can go directly into the genuine remanufactured parts process or be scrapped.

### Ordering required parts

Parts have been auto-allocated and have been shipped to dealers, expected to land in calendar week 5. If additional parts are required after allocation has landed to your dealer, please place a request via PRMS to PCNA parts support.

## Warranty processing

### Validity:

This workshop campaign will be carried out up to 12/15/2025 and will be closed by the specified date. Please note that warranty claims can only be processed before this date.

### Scope 1: Replacing lower part of front lid lock

- 718 Boxster (982)/Cayman (982)

Damage Code	WLG9 66 000
Repair Code	2

Working time	33 TU
--------------	-------

---

**Scope 2: Replacing lower part of front lid lock**

- 911 (991)

Damage Code	WLG9 66 000
-------------	-------------

---

Repair Code	2
-------------	---

---

Working time	33 TU
--------------	-------

---

**Scope 3: Replacing lower part of front lid lock**

- 911 (992)

Damage Code	WLG9 66 000
-------------	-------------

---

Repair Code	2
-------------	---

---

Working time	37 TU
--------------	-------

---

Please enter the campaign that was carried out in the Warranty and Maintenance booklet for the vehicle.

**Further information**

Work instruction	TI No. 185/20, Group 5, Service, WLG9
------------------	---------------------------------------

---

Vehicle list and allocation	See PCSS or attached VIN list for reference
-----------------------------	---

---

Technical Information	See PCSS or <a href="#">Aftersales Document Database</a> for reference
-----------------------	--

---

[WLG9 VIN List.xlsx](#)

**240.9 KB**

(108 views)

Created by [Ryan Cooney](#) on Jan 22, 2021 10:08 PM. Last modified by [Ryan Cooney](#) on Jan 26, 2021 1:03 AM.

931 Views [Report Abuse](#)

Categories: Cayman, Workshop Campaigns, 911 Carrera, Boxster

Tags : [workshop campaign](#), [982](#); [992](#), [wlg9](#)

Content and Topics	Personal	Manage	Create
Your Groups >	Edit Profile >	Admin Console >	Discussion >
Your Content >	Change Password >	PPN Administration >	Files >
Your Places >			Document >
			Collaboration >
			Document
			Blog Post >
			Poll >
			Event >
			Photo Album >
			Idea >
			Space >
			Group >

© 2021 Dr. Ing. h.c. F. Porsche AG. Legal notice. Copyright. Terms of use. Privacy Policy. Cookie Policy. [009](#)