

[Next Unread Message](#)

**View Message**

<b>Sent on</b>	01	28	2021	<b>Expires on</b>	02	16	2021
<b>From</b>	Quality Department, Parts Operations						
<b>Subject</b>	Accessory Part Return Request: 22 MDX Accessory Roof Rail						

American Honda has been notified by our supplier of manufacturing defect resulting in a potential cosmetic/appearance imperfections. Due to this investigation, American Honda is requesting all dealers to return any uninstalled inventory to American Honda for investigation and validation by the supplier.

Part Number: 08L02-TYA-200B  
 Lot Number(s) Affected: All lot dates prior to: 21022 (January 22, 2021)

**Return Request:**

Please return all uninstalled Accessory Roof Rails PN 08L02-TYA-200B prior to lot date 21022 still in your inventory. No Shipment Listing or Invoice is required for this return. These returns will not be charged against your SRA credit.

**Return iN OAR Procedure**

1. Complete the iN OAR procedures.
2. Use Reason Code "R" with eleven zeros for the Shipper Number.
3. Use Item Number "9999."
4. Enter "MDX Accessory Roof Rail Return" in the Remarks Section.
5. When approved, Print "Authorization Return document and labels" from the iN. Please return parts as normal with the "Return Authorization attached."
6. Return above mentioned accessory wheels on your returning DSO Truck or normal method of return.

Order adjustment requests (OARs) must be submitted by February 26th, 2021.

Thank you,

American Honda Motor Co., Inc.

CH/ms