

TECHNICAL TOPICS

POWERTRAIN



Noise From Engine Bay

16MY - Onward F PACE, F TYPE, XE, XF, XJ, Discovery, Range Rover, RR Sport, RR Velar equipped with AJ126 or AJ133

Customer Voice:

- There is a noise coming from the engine bay.

Technical Description:

- This topic is currently under investigation for the part numbers below:
 - C2D45642
 - LR071035

Status:

- Obtain a video/audio recording of the fault prior to repair.
- Inspect for any evidence of contamination of the tensioner and note any leaks present in the engine bay. Obtain pictures of any leaks identified.
- Complete any repairs as necessary and obtain a video/audio recording confirming the repairs.
- Hold the original parts for return. Raise an EPQR which includes the recordings and pictures taken during diagnosis and contact information (name, email address, and phone number) of someone who can serve as the point of contact for the shipping company to collect the original parts.

