

Classification:

EL18-034a

Reference:

ITB18-038a

COPYRIGHT© NISSAN NORTH AMERICA, INC.

Date:

January 28, 2021

2019 QX50; IPDM E/R CONFIGURATION AFTER UNIT REPLACEMENT

APPLIED VEHICLES: 2019 QX50 (J55)

This bulletin is no longer active.

Please discard previous versions of ITB18-038.

AMENDMENT HISTORY

| PUBLISHED DATE | REFERENCE | DESCRIPTION |
|-------------------|------------|-----------------------------|
| November 14, 2018 | ITB18-038 | Original bulletin published |
| January 28, 2021 | ITB18-038a | Bulletin no longer active |

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.