

GPOP - Issue Review System

Part Number: 68351145A\$, 68452822A\$, 68361944A\$, 68361946A\$, 68361945A\$, 68227735A\$, 68166861A\$, 68166860A\$, 68229331A\$, 68229334A\$, 68213474A\$, 68493755A\$, 68222860A\$, 68338073A\$, 68338082A\$, 68338086A\$, 68338084A\$, 68338083A\$, 68339359A\$, 68338085A\$, 68338087A\$, 68338088A\$, 68338079A\$, 68338081A\$, 68338080A\$, 68338078A\$, 68338076A\$, 55112833A\$, 55112842A\$, 55112845A\$, 55112846A\$, 68292244A\$, 55112843A\$, 68451038A\$, 68451039A\$, 68500323A\$, 68498798A\$, 68500321A\$, 68104203A\$, 68505966A\$, 68195027A\$, 68362490A\$, 68362491A\$, 68362492A\$, 68371466A\$, 68371467A\$, 68522631A\$, 68522632A\$, 68522633A\$, 68522634A\$

Part Description: WINDSHIELD

Issue Windshield cracked or blemish.

Description:

When customer comes in for a cracked windshield, please note the location of crack and take pictures before repair. Please send pictures to FCA Redacted Content or load to the warranty claims system.

~ _____ ~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.