



# Technical Service Bulletin

---

<b>Technical Service Bulletin:</b> TSB210005	<b>Released Date:</b> 18-Jan-2021
<b>Cruise Control Inoperative after OEM Software change - PACCAR™ Chassis</b>	

## Cruise Control Inoperative after OEM Software change - PACCAR™ Chassis

### Warranty Statement

---

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Information Only - OEM Related Matter Not Covered By Cummins® - Contact Appropriate OEM Dealer or OEM Representative For Additional Information

### Contents

---

#### Product Affected

Engines:

- B6.7 CM2350 B121
- ISB6.7 CM2350 B101
- ISL9 CM2350 L101
- L9 CM2350 L116B

Original Equipment Manufacturer (OEM):

- PACCAR

#### Issue

Symptom:

- Cruise control inoperative

Root Cause:

- Recent OEM software change

**Verification**

Verify recent OEM (PACCAR) chassis electronic control unit (CECU) software updates have been performed and the cruise control is now inoperative.

**Resolution**

Reference PACCAR TIB 03-072.

## Document History

Date	Details
2021-1-6	Module Created

---

**Last Modified: 18-Jan-2021**

---