

TT8745EN
January 06, 2021
Page 1 of 1

SUBJECT: Cooler Line Connections at Radiator — Freightliner M2 Chassis

MODELS AFFECTED: Freightliner M2 Chassis with Behr/Mahle Cooling Modules

Description of Concern:

Low transmission fluid level condition in Freightliner M2 chassis.

Potential Cause:

Transmission fluid leak at OEM-installed cooler line connections to transmission cooler at vehicle radiator.

Action:

For Freightliner M2 chassis with an Allison transmission, if transmission fluid loss is a concern and inspection of the transmission cooler line connections at the vehicle radiator reveals evidence of transmission fluid leakage, refer to **Freightliner Service Bulletin 20-086** for important information related to inspection and repair of the subject condition. Please note that repair work to resolve leakage at the transmission cooler is not the responsibility of Allison Transmission, and therefore is not warrantable by Allison Transmission.