



STAR ONLINE PUBLICATION



Case Number: S2018000013

Release Date: 12/04/2020

Symptom/Vehicle Issue: The concern includes the MIL/Check Engine lamp on. Upon further investigation there will be a fault code for P1300-00-FLYWHEEL SELF LEARNING – EOL active in the Powertrain Control Module (PCM).

Repair: Perform a “Phonic Wheel Reset” with the scan tool. The "Phonic Wheel Reset" procedure can be found under PCM>Miscellaneous Menu Option. Follow the on screen instructions.

Note: DO NOT DISCONNECT THE VEHICLE’S BATTERY FOR ANY REASON FOR A MINIMUM OF 25 MINUTES AFTER PERFORMING THE RESET PROCEDURE. DOING SO MAY CAUSE THE PCM TO BECOME UNRESPONSIVE.

If the P1300 is still present after performing the “Phonic Wheel Reset” procedure, perform the published diagnostic procedure located in Service Library for the fault code.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found