

SSM 49590 - 2020 Aviator - AWD - Rubbing/Clicking/Ticking Noise While Driving - Engine Mount Vacuum Hose Contacting Half shaft - Built On Or Before 15-Aug-2019

Some 2020 Aviator vehicles equipped with all-wheel drive (AWD) built on or before 15-Aug-2019 may exhibit a rubbing/clicking/ticking noise while driving that increases with vehicle speed. This may be due to the engine mount vacuum control tube contacting the left front axle half shaft. If the engine mount vacuum control tube is contacting the left front axle half shaft, reposition as needed.

APPLICABLE VEHICLES
2020 CAR: TV U611N AVIATOR