

Classification:

AT14-017E

Reference:

ITB15-010E

COPYRIGHT© NISSAN NORTH AMERICA, INC.

Date:

February 19, 2021

INFINITI; PROCEDURE TO CLEAN CVT TRANSMISSION FLUID COOLERS

APPLIED VEHICLES: 2013 JX (L50) - Built after 5N1AL0M(*)(*)DC 343902 // March 26, 2013
2014-2020 QX60 (L50) - **V6 engine only**

APPLIED TRANSMISSION: CVT

This bulletin is no longer active.

Please discard previous versions of ITB15-010.
Refer to the ESM for the fluid cooler cleaning procedure.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
March 12, 2015	ITB15-010	Original bulletin published.
September 9, 2015	ITB15-010a	APPLIED VEHICLES section revised
April 7, 2016	ITB15-010b	APPLIED VEHICLES section revised
April 24, 2017	ITB15-010c	APPLIED VEHICLES section revised
October 31, 2019	ITB15-010d	APPLIED VEHICLES and PARTS INFORMATION sections revised
February 19, 2021	ITB15-010e	Bulletin no longer active

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.