

Reference	SSM73653
Models	F-PACE / X761
Title	F-Pace 18MY Deployable Side Steps fail to initialise
Category	Accessories
Last modified	28-Nov-2017 00:00:00
Symptom	Electrical Accessories

ContentIssue:

Technicians are unable to initialise the Deployable Side Steps after fitment on F-Pace 18MY year vehicles

Cause:

Technicians are incorrectly fitting the 17MY Control Module (Part Number T4A7494) to 18MY Vehicles

Action:

For 18MY vehicles, a separate Harness (Part Number T4A14752) and Control Module (Part number T4A16372) are required

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.