



STAR ONLINE PUBLICATION



Case Number: S2108000041

Release Date: 2/11/2021

Symptom/Vehicle Issue: Check Engine Light On, U0422-00 Implausible Data Received From Body Control Module Is Active In The HCP

Discussion: The check engine light may be illuminated. Upon scanning the vehicle DTC U0422-00 Implausible Data Received From Body Control Module Is found Active in the HCP (Hybrid Control Processor).

Diagnosis: The DTC diagnostic procedure for the PIM (Power Inverter Module) should be used. This will lead to BCM Communication Diagnostic Procedure being performed. Follow the diagnostic procedure.

Repair: If after performing the diagnostic procedure and replacing the BCM the U0422-00 is still active. Do Not Replace Any Other Components. This issue is being investigated by engineering.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found