
PuMA measure

Touring case - play in fixture on case holder

US 65477074-01 - 02/02/21

Complaint:

The F900XR touring cases have considerable play and do not appear to be robust.

Cause

There is a lot of clearance between the hook rail of the touring case and the case holder.

Measure

This play is desired and necessary to fulfil the luggage system requirements for driving stability and operational stability.

Validity information

Model series:	[K84]
Engine range:	[ALL]
Body style:	[ALL]
Fault codes:	[]
Production period:	-

Repair overviews

Attachments

Number of attachments: 1