
PuMA measure

ISTA: Remaining distance is reset after programming

US 65493877-01 - 02/02/21

Complaint:

While programming the TFT instrument panel with ISTA, the "Remaining distance until next service" is sometimes reset to an implausible value.

Cause

Fault in software
(TFT instrument panel (B-KOMBI)/ ISTA)

Measure

Correct remaining distance must be subsequently reset manually with ISTA.

A remedy is expected with ISTA 4.26.1; the automatic setting of the remaining distance with ISTA will then be activated after programming.

Validity information

Model series:	[K80, K82, K81, K51, K84, K83, K50, K53, K52, K54, K67, K69, K08, K09]
Engine range:	[ALL]
Body style:	[ALL]
Fault codes:	[]
Production period:	- (With TFT / Connectivity only)

Repair overviews
