

Reference	SSM73487
Models	Discovery Sport / L550 Range Rover Evoque / L538
Title	L550 and L538 - Front Seat Manual Height Adjuster Cover - Fitment
Category	Body
Last modified	29-Nov-2017 00:00:00
Symptom	101000 Seating
Attachments	1Attachment7.pdf (1Attachment7.pdf)

ContentIssue:

The plastic cover of the front seat height adjuster lever on vehicles with manually adjustable seats can break on removal, leaving it loose when refitted and likely to become adrift (see attachment).

Cause:

The fastening feature (clips) on the inside face of the trim can be broken, resulting in a lack of retention.

Action:

When removing the trim for access purposes during any rework of the front seat, the original trim must be discarded, and a new trim ordered and fitted.

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.