

9002743 01/23/2013 MY12, 13 LC

GPOP - Issue Review System

Part Number: 05028799A\$, 05028798A\$

Part Description: Sill Cladding

Issue Description: If a sill cladding is being replaced, please ensure the foam is cleaned out of all clip slots in the body side and fender to ensure proper retention of the replacement part can be achieved.

~_____~

Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.