

Model series 167 - Humming noise emitted by speakers

Topic number	LI82.27-P-072402
Version	1
Function group	82.27 - Engine sound system
Date	2/19/21
Validity	Model series 167 equipped with M256 engine
Reason for change	

Complaint

If the exhaust flap is operated or the drive program is changed within 10 seconds of the engine being started, an audible humming noise may emit from the speakers.

Cause

Current sound amp (N40/3) software release

Remedy

New sound amp (N40/3) software is currently in development. This document will be updated once it is released.

Meanwhile, avoid toggling the drive program or the exhaust flap with 10 seconds of an engine start to avoid the possibility of the complaint occurring.

Note: Do not replace any parts as this will not remedy the complaint

Symptoms
Power generation > Engine noise > Noise
Power generation > Engine noise > Malfunction, sound generator
Power generation > Exhaust system > Noises > Noise
Chassis/suspension > Noises > Humming/droning/throbbing
Communication/information > Entertainment > Audio/Sound > Speakers emit interference noise

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note