



Technical Service Bulletin

Technical Service Bulletin: TSB210060	Released Date: 16-Mar-2021
On-Highway Natural Gas Engine Control Module (ECM) Calibration Update to Monitor Exhaust Manifold Pressure	

On-Highway Natural Gas Engine Control Module (ECM) Calibration Update to Monitor Exhaust Manifold Pressure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- B6.7N CM2380 B150B
- L9N CM2380 L124B
- L9N CM2380 L130B
- ISX12N CM2380 X120B

Issue

The parameter to monitor exhaust manifold pressure is **not** available using the recommended Cummins® electronic service tool or equivalent.

Verification

Use the electronic service tool to verify the parameter “Exhaust Manifold Pressure” is **not** available to be monitored.

Resolution

To monitor exhaust manifold pressure using the electronic service tool, update the engine control module (ECM) calibration dated below or later.

Engine	ECM Calibration Date
B6.7N CM2380 B150B	23 September 2020
L9N CM2380 L124B/L130B	24 September 2020
ISX12N CM2380 X120B	8 October 2020

Service Instructions

Reference procedure 019-032 in Section 19 of the corresponding Service Manual to calibrate the ECM.

Document History

Date	Details
2021-3-16	Module Created

Last Modified: 16-Mar-2021
