Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

instrum

DESCRIPTION:

If an Over The Air Software Update (OTA download) fails, and car is transported to a workshop, please follow fault tracing and diagnostic advice under "Service".

OTA = Over The Air

CSC Customer Symptom Codes

Code	Description						
24	Diagnostic communication/Remote diagnostic connection to vehicle does not work						
1Z	Service/repair/Software update failed						
52	Remote update/Does not work						
1C	Service/repair/Administrative and Factory scheduled maintenance						
2V	Technician information/Software/Vehicle communication/Not for warranty use						

DTC Diagnostic Trouble Codes

Vehicle Type

Туре	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
534						2021-9999		0000001-0999999	202007-999952

Technical Journal 35798.3.0

SERVICE:

Connect VIDA, and read out the car.

Check which control units that are not ok, use Software Download Tab in VIDA, Advanced.

Check which nodes that are responding in Diagnostic session and also in Programming session.

Try to perform a Total Upgrade.

If nodes are not responding, try to do a 12V battery reset, and check again.

If you still cannot get the nodes to respond, please contact Retailer Technical Support

Warranty claim info:

To get warranty claim accepted for a job described in this TJ, please use following data: VST op number 36004-2 (0.7hr), CSC 52

VST Operation Number

VST Operation Number	Description					
36004-2	Software control module downloading					

LABOR TIME:

Labor time subject to change without notice.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report Polestar" and sub concern area "Support needed Polestar", use function group 3000.

Page 2 of 2 2021-03-05