

Technical Journal

TITLE:

ESM Communication DTC's

REF NO: TJ 35888.1.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7515		ISSUE DATE: 2021-03-03	STATUS DATE: 2021-03-10
FUNC GROUP: 3953	FUNC DESC: Loudspeaker; loudspeaker cables	Page 1 of 2	

DESCRIPTION:

To support the fault tracing and repair in VIDA, if the listed DTC's are set separately or in combination, please follow instructions under "Service".

ESM = Exterior sound module

CSC Customer Symptom Codes

Code	Description
6J	Text window and warning symbol/Low battery
7G	Text window and warning symbol/Yellow symbol and text message
IV	Text window and warning symbol/Text message
39	Sounds and speakers/Warning and notification sounds not audible
IB	Speakers/Does not work

DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
BECM	U007388	Intermittent
ESM	U002888	Intermittent
VCU1	U112700	Intermittent

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
534							2021-9999	19	0000001-9999999	202007-999952

Technical Journal 35888.1.0

SERVICE:

Replace front ESM unit according to VIDA instructions.

Warranty claim info:

To get warranty claim accepted for a job described in this TJ, please use following data:

VST OP number: 38401-2 (0.4hr) and applicable CSC

VST Operation Number

VST Operation Number	Description
38401-2	Exterior sound module (ESM/ESMR) replace

LABOR TIME:

Labor time subject to change without notice.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed Polestar", use function group 3953.